WinQbase


WinQbase 2.63 Trial Database
Window
Edit
Options
Help
Menu
Instrument Inventory
Inventory parameters
Test report parameters
Users
Groups of instruments
Back up
Supplements
Calibration procedures
Exit
Group of instruments
Multimeters
WinQbase
c:\program files\meatest\winqbase\trialdata\
8. října 2007
John Brown
Inventory, calibrations, repairs
NUM

WinQbase

Basic features

Inventory of:

- **all meters in calibration laboratory (company)**
- **calibration certificates**
- **calibration procedures**

Other features:

- **various methods of sorting of meters and calibrations**
- **7 levels password protection**
- **creating, editing and printing of calibration certificates**
- **backup**
- **history of records**

WinQbase


WinQbase
Registration card of meter A
Registration card of meter B
Calibration No.5
Calibration No.4

WinQbase

Registration card of instrument



WinQbase

Calibration record



WinQbase

Supplements



WinQbase



Choice of meter to be calibrated (UUT)

Pass to the inventory of calibrations.
New calibration adding

Choice of appropriate calibration procedure.

Automatic or semiautomatic calibration

Saving of new calibration report into inventory of calibrations. Printing.